

Sent: Tue 9/5/2017 5:38:01 PM
Subject: FW: question about SOW for AS/SVE
[Pages from Tower Standard REI Report 2016 pages 1-100.pdf](#)

Bob Egan

Corrective Action Manager

Underground Storage Tanks Section

RCRA Branch

EPA Region 5

(312) 886-6212

(312) 692-2911 (fax)

From: Egan, Robert
Sent: Tuesday, September 05, 2017 12:27 PM
To: Sundar, Bhooma <sundar.bhooma@epa.gov>
Subject: RE: question about SOW for AS/SVE

Hi Bhooma,

Here is part of a report written by REI, the state PECFA contractor. I had to cut it up into several parts, and will send them to you and Conor. I will also add you to the user list for the epaosc.org website, where a number of reports are on the document list along with the 4DIM images which show the plume and soil source area based on the LIF and MiHPT work. For those, you will need to have the IT folks download the 4DIM viewer from the website.

I will add your names this afternoon. Please let me know if you have any problems accessing the information.

Bob

Bob Egan

Corrective Action Manager

Underground Storage Tanks Section

RCRA Branch

EPA Region 5

(312) 886-6212

(312) 692-2911 (fax)

From: Sundar, Bhooma

Sent: Tuesday, September 05, 2017 12:03 PM

To: Egan, Robert <egan.robert@epa.gov>

Cc: Neal, Conor <Neal.Conor@epa.gov>; Kamke, Sherry <Kamke.Sherry@epa.gov>

Subject: RE: question about SOW for AS/SVE

Hi Bob,

Could you please share the source characterization report for the Tower Standard LUST site?. Any other supporting information would also be helpful for us to contribute in a meaningful way.

Thanks.

Bhooma

From: Egan, Robert

Sent: Thursday, August 31, 2017 7:14 AM

To: Sundar, Bhooma <sundar.bhooma@epa.gov>

Cc: Neal, Conor <Neal.Conor@epa.gov>; Kamke, Sherry <Kamke.Sherry@epa.gov>

Subject: RE: question about SOW for AS/SVE

Thank you, Bhooma. This is a good example to get me better acquainted with the process.

Bob Egan

Corrective Action Manager

Underground Storage Tanks Section

RCRA Branch

EPA Region 5

(312) 886-6212

(312) 692-2911 (fax)

From: Sundar, Bhooma

Sent: Wednesday, August 30, 2017 4:26 PM

To: Egan, Robert <egan.robert@epa.gov>

Cc: Neal, Conor <Neal.Conor@epa.gov>; Kamke, Sherry <Kamke.Sherry@epa.gov>

Subject: Re: question about SOW for AS/SVE

Hi Bob,

After reading Mike's email, I recognize the time sensitive nature of this project. I browsed through the web for a latest pilot workplan and I came up with this. The attached document would be a good start for you to put together a work order.

Bhooma

From: Sundar, Bhooma

Sent: Wednesday, August 30, 2017 2:51:25 PM

To: Egan, Robert

Subject: Re: question about SOW for AS/SVE

Sure, No problem.

From: Egan, Robert
Sent: Wednesday, August 30, 2017 2:47:21 PM
To: Sundar, Bhooma
Subject: RE: question about SOW for AS/SVE

Thank you, Bhooma.

I will be working at home tomorrow. If you have a CD, can you e-mail the document to me?

If not, please place the report on my chair.

Thank you!

Bob Egan
Corrective Action Manager
Underground Storage Tanks Section
RCRA Branch
EPA Region 5
(312) 886-6212
(312) 692-2911 (fax)

From: Sundar, Bhooma
Sent: Wednesday, August 30, 2017 2:42 PM

To: Egan, Robert <egan.robert@epa.gov>; Neal, Conor <Neal.Conor@epa.gov>
Cc: Kamke, Sherry <Kamke.Sherry@epa.gov>
Subject: Re: question about SOW for AS/SVE

Bob,

I am working from home today and don't seem to have an electronic copy of AS/SVE work plan. I will bring the CD or the hardcopy with me when we meet tomorrow.

Bhooma

From: Egan, Robert
Sent: Wednesday, August 30, 2017 1:38:13 PM
To: Neal, Conor; Sundar, Bhooma
Cc: Kamke, Sherry
Subject: question about SOW for AS/SVE

Bhooma and Conor,

Thank you for offering to assist with the Tower Standard LUST site. I look forward to giving you some background site information.

As a first question, do either of you have a Statement of Work/Task Order/Work Plan for an Air Sparge/Soil Vapor Extraction Pilot Scale Test at a site? Mike Harris wants us to move quickly to get a contractor on board to do this work at the site. I have access to a SF contractor but need an example SOW to draw information from for writing up my task order.

And secondly, are either of you a WAM or COR? I am a COR but we are looking for a backup if one is needed.

Thank you for your help.

Bob

Bob Egan

Corrective Action Manager

Underground Storage Tanks Section

RCRA Branch

EPA Region 5

(312) 886-6212

(312) 692-2911 (fax)